

「光纖交換機」財物採購案

需求說明書附件 3-現有及新購光纖交換機韌體版本更新

fiber-3f-1	Kernel: 2.6.14.2 Fabric OS: v7.4.1d Made on: Thu Jul 14 23:11:54 2016 Flash: Thu Mar 30 03:03:07 2017 BootProm: 1.0.11
fiber-3f-2	Kernel: 2.6.14.2 Fabric OS: v8.0.2c Made on: Tue May 30 17:38:00 2017 Flash: Wed Mar 21 22:02:54 2018 BootProm: 1.0.11
fiber-3f-3	Kernel: 2.6.14.2 Fabric OS: v8.0.2c Made on: Tue May 30 17:38:00 2017 Flash: Sat Oct 6 21:46:35 2018 BootProm: 1.0.11
fiber-3f-4	Kernel: 2.6.34.6 Fabric OS: v8.2.1c Made on: Fri Jun 28 14:35:15 2019 Flash: Mon Mar 22 18:54:26 2021 BootProm: 3.0.32
fiber-5f-1	Kernel: 2.6.14.2 Fabric OS: v7.4.1d Made on: Thu Jul 14 23:11:54 2016 Flash: Thu Mar 30 02:26:21 2017 BootProm: 1.0.11
fiber-5f-2	Kernel: 2.6.34.6 Fabric OS: v8.2.1c Made on: Fri Jun 28 14:35:15 2019 Flash: Mon Mar 22 18:44:28 2021 BootProm: 3.0.32
fiber-bk1	Kernel: 2.6.14.2 Fabric OS: v8.1.2h Made on: Mon Jul 8 22:05:54 2019

	Flash: Tue Nov 5 16:48:18 2019 BootProm: 1.0.11
fiber-bk2	Kernel: 2.6.14.2 Fabric OS: v8.1.2h Made on: Mon Jul 8 22:05:54 2019 Flash: Fri Nov 8 14:28:39 2019 BootProm: 1.0.11